Upload Flight Log from Spry Drone V1.1

The Spry drone can record the last 10 minutes' flight data.

UnZip SpryLogTool

1. Run SpryLogTool.exe **(Only works on Win7 or Win10 system)**; 2. Connect USB with Spry's USB port and waiting 30 seconds; 3. Click the "UploadLog" button on the download software; 4. When the upload is complete, click Save the file to the computer; 5. Send the files to Swellpro support team; 6. If fail to upload, then re-start from Step 5.

** SpryLogTool only runs in Win7 & Win10 PC. Don't support iOS.

** Got report some Win7 PC can't run this FirmwareTool. If you have the same problem, try to download a plugin and try:
https://www.microsoft.com/en-US/download/confirmation.aspx?id=42642

** Shut down all the Anti-virus software and Remove the U disk from PC.